



Flat Rate Repair Pricing



Price does not include dispenser board repair if needed. Additional charge for rodent damage					
DISPENSER	Repair Code	Part	Repair	Warranty	Price
	REP-00019	TCDU (800 Note Fixed)	Hantle/Genmega TCDU Dispenser Complete Refurbishment	6 Month	\$249
				9 Month	\$279
	REP-00020	MCDU/RCDU/HCDU Single Cassette	Hantle/Genmega MCDU/RCDU/HCDU Single Cassette Dispenser Complete Refurbishment	6 Month	\$249
				9 Month	\$279
	REP-00021	MCDU Multiple Cassette	Hantle/Genmega MCDU Multiple Cassette Dispenser Complete Refurbishment	6 Month	\$379
				9 Month	\$399
REP-00022	SCDU (1,000 Note Cassette)	Hantle/Genmega SCDU Dispenser Complete Refurbishment	6 Month	\$249	
			9 Month	\$279	
REP-00023	Dispenser Board Repair	Hantle/Genmega Dispenser Board Repair Complete Refurbishment	6 Month	\$125	
Additional charge for rodent damage					
CASSETTE	Repair Code	Part	Repair	Warranty	Price
	REP-00024	MCDU/SCDU/RCDU/HCDU	Hantle/Genmega Cassette (All Models) Complete Refurbishment	6 Month	\$149
MAINBOARD	Repair Code	Part	Repair	Warranty	Price
	REP-00025	Mainboard	Hantle/Genmega Mainboard Software Upgrade	6 Month	\$75
	REP-00026	Mainboard Extensive	Hantle/Genmega Mainboard Extensive Component Repair	6 Month	\$125
PRINTER	Repair Code	Part	Repair	Warranty	Price
	REP-00027	All Printers	Hantle/Genmega Printer (All Models) Complete Refurbishment	6 Month	\$249
	REP-00028	Printer Board	Hantle/Genmega Printer Board Complete Refurbishment	6 Month	\$125
LCD	Repair Code	Part	Repair	Warranty	Price
	REP-00029	LCD (Screen)	Hantle/Genmega LCD 5.7" & 10.4" Complete Refurbishment	6 Month	\$249
	REP-00030	LED Upgrade	Hantle/Genmega LED Upgrade	6 Month	\$125
POWER SUPPLY	Repair Code	Part	Repair	Warranty	Price
	REP-00031	Power Supply	Hantle/Genmega Power Supply Complete Refurbishment	6 Month	\$169

All repairs carry a standard 6 or 9 month warranty option select repairs.

Premier Technology Systems, Inc
 9000 Sheridan St, Ste 148,
 Pembroke Pines, FL 33024
 E info@gotechsf.com
 O (954) 923-8033
 F (954) 337-5814