



Flat Rate Repair Pricing



Price does not include dispenser board repair if needed. Additional charge for rodent damage					
	Repair Code	Part	Repair	Warranty	Price
DISPENSER	REP-00001	1K Note Dispenser	Hyosung 1,000 Note Dispenser Complete Refurbishment	6 Month	\$239
				9 Month	\$299
	REP-00002	2K Note Dispenser	Hyosung 2,000 Note Dispenser Complete Refurbishment	6 Month	\$239
				9 Month	\$299
	REP-00003	4K Note Dispenser	Hyosung 4,000 Note Dispenser Complete Refurbishment	6 Month	\$239
				9 Month	\$299
	REP-00004	6K-8K Note Dispenser	Hyosung 6-8,000 Note Dispenser Complete Refurbishment	6 Month	\$239
				9 Month	\$299
	REP-00005	Drawer Style Dispenser	Hyosung Drawer Style Dispenser Complete Refurbishment	6 Month	\$239
				9 Month	\$299
	REP-00006	Dispenser Board Repair	Hyosung Dispenser Board Complete Refurbishment	6 Month	\$239
				9 Month	\$299
Additional charge for rodent damage					
	Repair Code	Part	Repair	Warranty	Price
CASSETTE	REP-00007	1k & 2k Note Cassettes	Hyosung 1,000 and 2,000 Note Complete Refurbishment	6 Month	\$169
				9 Month	\$189
	REP-00008	2K Note Cassette	Hyosung 2,000 Note Complete Refurbishment	6 Month	\$169
				9 Month	\$189
KEYPAD	REP-00009	All Hyosung/Hantle Keypads	Hyosung or Hantle Complete Refurbishment	6 Month	\$189
MAINBOARD	REP-00010	Mainboard	Hyosung Mainboard Reprogram	6 Month	\$75
	REP-00011	Mainboard Extensive	Hyosung Mainboard Extensive Component Repair	6 Month	\$125
PRINTER	REP-00012	All Hyosung/Hantle (Tranax) Printers	Hyosung/Hantle (Tranax) Printer (All Models) Complete Refurbishment	6 Month	\$249
	REP-00013	Hyosung/Hantle (Tranax) Printer Board	Hyosung/Hantle (Tranax) Printer Board Complete Refurbishment	6 Month	\$125
REP-00014	EMV Firmware Upgrade	Hyosung 1500SE EMV Firmware Upgrade	6 Month	\$75	
LCD	REP-00015	LCD (Screen)	Hyosung LCD 5.7" & 10.4" Complete Refurbishment	6 Month	\$149
	REP-00016	LED Upgrade	Hyosung LED Upgrade	6 Month	\$179
POWER SUPPLY	REP-00017	Power Supply	Hyosung Power Supply Complete Refurbishment	6 Month	\$169
CARD READER	REP-00018	Card Reader	Hyosung EMV Card Reader Complete Refurbishment	6 Month	\$220

All repairs carry a standard 6 or 9 month warranty option select repairs.

Premier Technology Systems, Inc
 9000 Sheridan St, Ste 148,
 Pembroke Pines, FL 33024
 E info@gotechsf.com
 O (954) 923-8033
 F (954) 337-5814